

Aug 1845 *Bank of New Bedford* *Edw. Allen* *1845*
1845 *1845* *1845* *1845* *1845* *1845* *1845* *1845* *1845* *1845*
1845 *1845* *1845* *1845* *1845* *1845* *1845* *1845* *1845* *1845*

Rep in bottom new top new main made all new main rigging
 Calks Chumans Shit & Copper in 1845 - In August 1850
 Apper on bottom repaired. Ship put in good order.
 Bank of New Bedford from page 66
 In July 1865 had new Smith's heads - new bulwarks
 outside in forward of foremast - Paint new upper
 deck. Lp caulked and put in good order. One
 half new copper in bottom - Bank appears to
 be in fair order for a short voyage. In Sept 1867
 repaired had a large quantity of plank put on
 bottom. Dark caulked and over bottom sheathing
 and coppered put in fair order. April 1872 new
 upper deck and 12 new deck knees - 2 upper deck beams
 Coppered - vessel in good order.

Mar 1846 *Bank of New Bedford* *Edw. Allen* *1846*
1846 *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846*
1846 *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846*

In 1846 hauled in the masts & lengthened 12 ft. Ceiling all
 out of hold & timbers nearly all new. In entire new top
 In 1846 frames caulked all over bottom sheathing &
 coppered. Main rigging new for 1846 in old but
 good. Fair rate old ship.
 In Oct 1849. Lp caulked.
 bottom coppered. Ship put in good order.
 Isaac in. West Agent. In July 1853 ship caulked
 all over bottom sheathing & coppered, & put in good
 order - In the Spring of 1858, top caulked and bottom coppered.
 Bank in good order.

June 1846 *Bank of New Bedford* *Edw. Allen* *1846*
1846 *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846*
1846 *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846*

In 1840 had new top, In 1843 new bottomed, caulked
 all over bottom sheathing In 1846 new upper deck
 and some new beams. Top caulked and a bottom
 coppered ship in good order. Tugging old but good
 and in good order. In 1849, new top caulked &
 put in good order. Bottom coppered, good old ship.
 In 1852 had 14 new stencions and some other repairs
 about top. Caulked all over chumans sheathing & coppered
 ship appears to be in fair order for a voyage. In June
 1855. had top caulked & bottom coppered. Ship appears in
 fair order. In Sept. 1859, had new lower deck and frame
 top and benes caulked - wood ends and garboard & x
 arranged - bottom coppered - Ship appears to be in
 fair order. In June 1862 had several planks put in
 bottom - had some new timbers in the wake of cabin - Ship caulked all over
 bottom sheathing and coppered. Bank from all that can be seen appears in fair order.
 (See previous page)

June 1846 *Bank of New Bedford* *Edw. Allen* *1846*
1846 *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846*
1846 *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846* *1846*

In 1846 had ceiling out of lower hold all bad timbers
 replaced with new, Cured a new bottom refastened
 new plank outside from bends up, new stencions
 new rails, new bows, Ship put in good order. Caused all
 over sheathing - Chumans & top. Main tugging new
 Fore tugging & yars head. In October 1848 top caulked & bottom
 coppered ship in fair order. In 1851 top caulked & bottom
 coppered ship in good order. In Sept 53 had the ceiling all
 out of lower hold. No new timbers fast. Ceiled new. New
 breast hook. New wales. New lower deck & frames. Ship
 caulked all over. Bottom sheathing and coppered. Ship in
 good order. In Sept 1856, had her top caulked and bottom
 coppered, - ship put in good order.
 In June 1864, top caulked, bottom coppered -
 Ship appears to be in good order - In April 1869
 had new upper deck & frame & new transoms
 repaired wherever needed put in good order
 Caulked all over bottom sheathing & coppered