

Ship Europa of New Bedford
 E. C. Jones Agent. Built in Mattapoisett in 18
 380 tons Copper fastened 2 C. C. good Anchors good
 Decks 2 Rate A. 1/2

Remarks

In 1851 caulked sheathed and coppered —
 In the spring of 1854 had her top caulked
 and Bottom coppered, Ship in good order
 also Bottom caulked and sheathed —
 In May 1856 had her top caulked and Bottom
 coppered, Ship put in good order —
 In Nov. 1860 had her top caulked and
 Bottom coppered Ship put in fair order —
 In June 1862 had 1/4 new sheathing on
 bottom — wood end stonings caulked — top caulked
 bottom coppered — 3 new masts — Ship in good order
 In Sept 1867 caulked sheathed & coppered
 and put in good order In 1871 top caulked
 bottom coppered ship put in good order

Choooner Eliza Jane of New Bedford
 Swift & Perry Agt Built in Hibernia in 1849
 127 tons Built with Copper fast Chains extra large
 Anchors extra large Deck Rate A 1/2

In 1861 caulked all over Bottom cemented
 & coppered Scho in good order

Brig Pioneer of New Dungen Williams & Barry
 Built in Brunswick 20 in 1840 335 tons Built with Copper fast
 3 large Chains Anchors Heavy Decks Rate A 2

Built for the U.S. Government of Live Oak
 Very heavy timbered and heavy fastened

In 1858 was caulked all over, bottom sheathed
 from the top of the water to below light water
 mark with 2 in Oak plank. Sheathing caulked
 fitted in about the stern and fitted around
 the bows and Iron plated 7 foot deep and 18
 foot back from the stem In April 1862 taken
 on the way bottom caulked, and sheathing
 above caulked & painted, vessel appears to be
 in good order

Scho Emerald of Lippican B. B. Wand
 Built in Kingston N.H. 1838 100 tons Iron & Copper fast
 3 cc 1/16 & 1/16 Anchors Heavy Deck Rate A 3/2

In 1839 caulked all over and put in fair order
 in Fairhaven. Bottom sheathed & coppered. In April
 1862 top caulked Bottom coppered scho in fair
 order In the Spring of 1863 rebuilt and
 put in good order bottom painted In April
 1871 had some repairs about the top. top
 put in good order caulked all over and
 coppered on the skin Brig appears to be in
 good condition