
55
62
W. CROSS
Night and Sunday Watchman. - No Clock. - 300' 1" Hose. - Power and Heat: Steam. - Fuel: Coal. - Lights: Gas. -
Chas. Heurich. - Bottling. -
Office
Bottling & Shipping
Cold Storage
Covered Yard
Skylights
Concrete Floor
Lumber 10'
Lumber Shed
1
Primary School No 29.
Furnace Heat. - No Lights. -
Lumber 12'
Dry House. - Hot Air. -
Lumber Shed
Sawing
Sawing 1st Finishing 2nd & 3rd
Office 1st
2
D. W. Wilfson & Sons. - Furniture Mfr.
No Watchman. - Fuel: Coal. - Lights: Gas. - Power and Heat: Steam. - Fire Pails Throughout. - V.P. and Hose as Shown. - Steam Jet in Dry House and Sawings Vault. -
3
Foundry
Shed
Coke
Forge
Machine Shop
Side Lights
Pattern Shop. Carpr.
Office 2nd
4
Maryland Foundry Co. -
No Watchman - Fuel: Coal & Coke. - Power and Heat: Steam. - Fire Pails and Barrels of Water. - Lights: Gas. -
W. WEST
Night & Sunday Watchman. - No Clock. - Power: Electric, own Motor. - Lights: Electric. - Barrels of Water and Fire Pails Throughout. - 100' 1" Hose. -
Baltimore Sash and Door Co. -
Carpr 2nd
Stock Room. -
Glazing Room.
Print.
Office 1st
Ware House
Moulding Sheds. -
Full of Small Skylights. -
8
Factory
Baltimore Tack Co. -
Ware House. - Packing Room 2nd
Storage Shed
D. W. Wilfson & Sons - Furniture Mfr.
Ware Houses. -
No Watchman. - Power: Steam. - Heat: Stoves. - Fuel: Coal. - Lights: Gas. - V.P. and Hose as Shown. - City Water. -
S. HOWARD
62
63
Plum Alley
Shed
Barrel Storage
7
Ruins.
Dilapidated
No Watchman. - Heat: Steam. - Lights: Gas. - Fuel: Coal. - Barrels of Water and Fire Pails. - Half Barrels and Pails of Sand. -
Sharp
Barrels Repaired
6
American Steel Buckle Co. and Catch on Clasp Co.
Small Piles of Lumber
No Watchman. - Power & Heat: Steam. - Fuel: Coal. - Lights: Gas. - Fire Pails Throughout. - City Water. -
Peach Alley
Lumber 10'
Lumber 12'
Lumber 8'
Moulding Shed
Storage
5
F. X. Ganter. - Mfrs. of Show Cases, Store Fixtures Etc. -
Glass Room 1st
Sales Room 2nd
Varnishing 3rd
Office 2nd
Leadenhall
F. X. Ganter. -
Night and Sunday Watchman. - Newmans Stationary Watchmans Clock 8 Stations Hourly Rounds. - Power and Heat: Steam. - Fuel: Coal and Waste. - Fire Pails Throughout. - V.P. Chemical. - Heat. Pipe and Hose as Shown. - Hydrant Hose Cart. - Hydrants to be Placed in Yard. - Permit Granted by City. -
Stockholm
10" W. Pipe
Baltimore Arms Co. -
Machine Shop 1st
Baking
Night and Sunday Watchman. - Amer. Watchmans Time Detector. Hourly Rounds. - Power & Heat: Steam. - Fuel: Coal. - Lights: Gas. - Fire Pails Throughout. -
Brick Floor
Tin Clad Roof
10
Ware House
Packing 1st
Storage 2nd
Brick Floor 1st
Wm Grecht & Co. - Canned Goods. - Tin Can Mfr. -
No Watchman. - No Heat. - Fuel: Coal. - Fire Pails and Barrels of Water Throughout. - Lights: Gas. - Power Steam.
9
The Slingluff & Glacken Chemical Co.
Yacht.
Office & Shipping Room 1st
Polishing & Cutting
Yard.
Cutting Stone
Crusher
Stored Stone
11
Sawing Stone
Cutting & Polishing
Engine Room
Brick Floor
No Watchman. - Power and Heat: Steam. - Fuel: Coal. - Lights: Gas. - Fire Pails Throughout. -
I. Hilgartner & Sons. - Interior Builds. Marbles Etc.
Chesapeake Oil Co. -
Paints, Oils, Etc. - No Watchman - Power and Heat: Steam. - No Lights. -
Shed
Retort
Crusher
Boxes of Glass
12
Coal Pockets.
Coal Yard.
Henry Seim Co. - Window Glass Ware Hos. -
Glass Storage
Office
B. & O. R. R.
W. OSTEND
Scale of Feet.
0
50 40 30 20 10 0 50 100 150
Y A C A N T
I. Hilgartner & Sons. -
Night and Sunday Watchman. - Electric Clock, 8 Stations, Half Hourly Rounds. - Power and Heat: Steam. - Fuel: Coal. - Lights: Electric. - Fire Pails Throughout. - 500' 1" Hose. -
78