17

18

DRY OR LINCOLN

7

A.M.E. Hall

20

19

Public School. (Colored)

Colored Church.

GAY

2

THIRD

GRAIN & FLOUR EXCHANGE.

21

FOURTH

22

FIFTH

4

Grain & Flour.

Hay.

Bank.

Down's Building.

MARKET

24

23

M. E. Church.
20' to Eaves. Heat: Furnace. Lights: Lamps.

Cemetery.

FRANKLIN OR LOW

14

25

3

N. Exposure.

100' to 1-Sto. Fr. Dwlg.

N. Sixth St.

May 1901
DENTON
M'D.

L. B. Towers Ice Fac.
No Watchman. No Lights. No Heat. No Fire Apps. Power: Steam. Fuel: Coal.

Denton Pass. Station

Queen Anne R.R.

No Exposure.

Ice Fac.

Elev. W.T. Cap. 700 Gal.

Large Quantity of Slabs in Small Piles.

No Exposure.

Hughes Lumber & Coal Co.
No Watchman. Barrels of Water and Fire Buckets. Power: Steam. Fuel: Waste. No Heat. No Lights. About 200,000 ft. Lumber in Yard.

Small Piles of Lumber.

Lumber 15' High.

Lumber Shed.

Coal Pocket.

Coal Pocket.

Small Piles of Lumber.

Queen Anne R.R.

Planing Mill.

Saw & Planing Mill.

Well.

No Exposure.

Queen Anne R.R.

No Exposure.

B. W. Parker Canning Wks.
(Not Completed.)

W. Ho.

Canning Ho.

Blr. Ho.

Boil.

Box Fac.

No Exposure.

No Exposure.

Reproduction
1955
Library of Congress

Scale of Feet.
50 40 30 20 10 0 50 100 150