Journal from ..... towards .....

H	K	F	COURSES.	WINDS.	Therm. Air.	Therm. Wet.	Barom.	REMARKS. 18
1								our ledge, wind moderate very fast
2								at 10 P.M. wind light and fine
3								rigging fast. Commenced to heave a-
4								-ll foame off, sounded pumps found
5								she was leaking about 210 strokes
6								per hour, let go anchor, and
7								rigged boom out astern for rudder
8								secured away the wreck of jibboom
9								and head gear. Wind S.S.W.
10								
11								
12								
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								

COURSE.	Distance.	Lat.	Long.	Dist by Wheel.	No. Revolutions.	Lbs. Steam.	Cut-Off.	Coal Consumed.	Coal on Board.	Barometer.	Variation of Comp.
										29.80	

H	K	F	COURSES.	WINDS.	Therm. Air.	Therm. Wet.	Barom.	REMARKS. Tuesday 22nd 18
1								Shaped sail and went westward.
2								Schooner working well into a little cove
3								where we anchored with both anchors
4								and ledge on shore. Hoisted our
5								rudder on deck an unsure fitting
6								schooner leaking 210 strokes per hour
7								wind S.W.
8								
9								
10								
11								
12								
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								

COURSE.	Distance.	Lat.	Long.	Dist by Wheel.	No. Revolutions.	Lbs. Steam.	Cut-Off.	Coal Consumed.	Coal on Board.	Barometer.	Variation of Comp.
										30.00	

Journal from along the west coast towards Patagonia

H	K	F	COURSES.	WINDS.	Therm. Air.	Therm. Wet.	Barom.	REMARKS. Wednesday Oct. 25th 1876
1								All hands busily employed on the rigging
2								and rudder. Wind W.S.W. leaking 6
3								170 strokes per hour.
4								
5								
6								
7								
8								
9								
10								
11								
12								
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								

COURSE.	Distance.	Lat.	Long.	Dist. by Wheel.	No. Revolutions.	Lbs. Steam.	Cut-Off.	Coal Consumed.	Coal on Board.	Barometer.	Variation of Comp.
										29.80	

H	K	F	COURSES.	WINDS.	Therm. Air.	Therm. Wet.	Barom.	REMARKS. Thursday Oct. 26th 1876
1								Hung the rudder and fitted water
2								all ready for a start. Leak decreasing
3								all the time leaking 90 strokes
4								per hour. Calms and heavy rain
5								squalls.
6								
7								
8								
9								
10								
11								
12								
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								

COURSE.	Distance.	Lat.	Long.	Dist. by Wheel.	No. Revolutions.	Lbs. Steam.	Cut-Off.	Coal Consumed.	Coal on Board.	Barometer.	Variation of Comp.
										29.80	