

APPLICATION RECEIVED	PURPOSE OF APPLICATION	PERMIT		CONSTRUCTION COST	DATE OF COMPLETION	REMARKS
		NUMBER	DATE			
4/10/43	Repair sign	12678	4-16-43	—		
11/28/43	Inspection license 1944	19432	1/6/44	—		
2/5/45	" "	1945-28473	2/14/45	—	2/15/45 OK	
1/2/46	" "	1946 37494	1/15/46	—		
6/29/46	Replaster ceiling	44795	7/29/46	1000.00		405
1/10/47	Inspection license 1947	50215	2/13/47	----		405
6/26/47	Excavate and replace wall Remove n.b. partition,	56108	6/26/47	1000.00		405
12/17/47	Inspection license	63411	1/7/48	—		405
10/13/48	" "	1949 78603	12/28/48	—		405
10/31/49	Alter ^{for pool room} floor use 2nd flr	93192	10/31/49	10.00		405
12/9/49	Inspection license 1950	96107	2/1/50	—		405
10/7/50	" "	1951 109574	12/17/50	—		405
12/6/51	" "	1952 123707	1/8/52	—		405
1/23/52	" "	1952 124379	2/1/52	—		405 Basement
12/4/52	" "	1953 138223	1/29/52	—		405
3/7/53	" "	1953 145921	6/19/53	—		403-07
1-20-54	Permit basmt for ¹⁹⁵⁴ floor	156923	1-19-54	—	3-22-55	405
1-11-54	2 insp for 1954	157576	2-11-54	—	2-15-54	405-07
1-13-55	Inspection 1955	171317	1-12-55	—	1-17-55	403-7
		V-11540	ant 12-21-54 Recting 3-1-55			