

1813. Mr John Pitts Ironman Col^d of egg & ~~egg~~

Jan 5.	To Thinning lock 1/3 to 2 Shows 7/6 to 2 Moved 1/10	10 7/10
	To 2 keys & 1 back of Col ^d Bill lock 2/1	4 0/10
	To 1 Ax 12/6 to Stealing 18 6/3	18 9
March 4.	To Laying Shear & point Cauter 7/6	7 6
	To Laying Shank of Cauter 3/3	3 3
	To Laying Shear & Cauter 10/1 to Thinning Sore 1/3	11 3
	To point Cauter 2/6 to head on both 1/1	3 6
	To 2 3 hooks of Thinning 2/1 Show 3/9	5 9
	To point Cauter 2/6 to Laying Cauter & point 7/6	10
	To Mending 2 flukes 2/6 to 3 both 3/1	5
	To Sharp 2 Shears 2/6 to point 2 Cauters 5/1	7 6
April.	To Laying bar & wing 10/1 to 4 Shows 15/1	15 0
	To putting Irons to garden hoe 2/6 to Laying Cauter 6/3	8 9
May.	To Laying Cauter 6/3 to facing gun Stal 3/9	10 0
June 1.	To Sharp 4 Sets of Irons 8/1 to point Cauter 2/6	10 6
	To 2 Shows 7/6 to Mending 4 9 3/9	3 9
	To Laying Cauter & point 18 3/9 to Sharp 2 Cauters 1/6	10 3
23.	To point of the axle to the wheel a little bit	4 0
	To Laying wing & bar 10/1 to point 2/6 to Sharp 18 9 9	13 3
July 12.	To Sharp 2 Shear & point 2 Cauters 7/6	7 6
	To Sharp & point 2 Sets 7/6 to Mending bar 1/3	8 9
	To Laying bar & wing 10/1 to Sharp Shear 1/3	11 3
	To Laying Shear & point Cauter 7/6	7 6
	To Sharp Set of 2 to 2 Verts 1/1 to point Cauter 2/6	5 6
	To 2 plates on collar board of Laying Cauter 6/3	8 3
	To Sharp Shear 1/3 to 4 Shows 15/1	16 3
	To Sharp Set of Irons 2/1 to Mending bar 1/3	3 3
Aug.	To point Cauter 2/6 to Sharp 2 Shows 2/3	4 9
	To point & Cauter 10/1 to Laying Shear 5/1	15
	To Sharp 3 Shears & 1 Cauter 4/6 to Laying Cauter 6/3	10 9
	To 3 Shows 5/9 to Sharp 15 harrow teeth 5/1	10 9
	To Sharp 2 Sets 4/1 to Sharp 2 Cauters 1/6 to 6 Shows 3/9	9 3
	To Sharp Shear & point Cauter 3/9 to Sharp 2 Cauters 1/6	5 3
	To Thinning 3 Shows 2/9 to 1 Mue 8 1/10	4 7
Sept.	To Sharp 3 Cauters 2/3 to point 2 Cauters 5/1 to Sharp 18 9 9	8 6
	To point 2 Cauters 5/1 to Sharp 3 Sets 6/1	11 0
	To amount carried forward	16 0 7/10