

1882

Amount brot over

\$ 27.47½

May 22 nd	To Laying plow shear. 150, Oyster Knives 50	2.00
27	Remove 1 pair shoes. 31, 2 straps on waggon 50, 81	
"	Sharpen 1 Brub hoe 25.	25
28	Mend Waggon run ch 20, 2 Staples 20.	40
	Sharpen 3 hoes. 75, 3 rivets in shov handle 30, 1 05	
March 1 st	1 Sett shoes. 125, (2 nd) 2 hooks for ^{double} single tree 25.	1.70
3	New Lay better 150.	1.50
7	1 Ring for waggon single tree	20
	1 plate 25 (10 th), 1 Sett shoes removed 62½,	87½
	2 Staples & 2 hooks for single tree	.50
	1 Staple 10. (13 th), repair 1 better 15.	.25
	1 bolt 10, put ring in chain 10.	.20
	2 Links 20, 2 hooks. 30, (14 th), 1 staple & bolt 30	.80
16 th	New Lay 1 better 150, (18 th), 2 Staples & 1 ring 30	1.80
	2 Staples & 2 rivets 30,	.30
23	2 Plow blades 100, Remove 1 shoe 16, 2 bolts 20, 36	
	1 bolt for waggon cap ring 50 Lay steel on better 75, 1 25	
25	Laying plow shear 150, refit & repair Cuff 25,	1.75
27	1 Sett shoes removed 62½ Laying Brub hoe 100,	1.62½
	1 bolt 10, (29 th), 1 rod for plow handles. 25.	.35
31	Take out wolf teeth 25, 1 pair shoes 62½	87½
April 1 st	Weld bar on plow shear 75, 1 bolt 10, 1 blade 50	1.35
	1 3 horse staple & hook 40 New Lay grub hoe 100	1.40
		\$ 50.08