

May 20/33

This Day comes in with S.W. wind and clear Bar 30.30 Crew getting hull ready for painting 4 P.M. S.W. wind and clear Bar 30.20 All is well So ends this day

May 21/33

This Day comes in with N.E. wind and rain Bar 30.25 Ernest Jennings and Jack Frates on watch 4 P.M. N.E. and cloudy Bar 30.35 All is well So ends this day

May 22/33

This Day comes in with S.W. wind and cloudy Bar 30.45 Crew scraping hull 4 P.M. S.W. wind and clear Bar 30.45 All is well So ends this day

May 23/33

This Day comes in with S.W. wind and fog Bar 30.50 Crew painting black on Starboard Side 4 P.M. S.W. wind and cloudy Bar 30.50 All is well So ends this day

May 24/33

This Day comes in with S.W. wind and clear Bar 30.40 Crew painting hull on Starboard Side 4 P.M. East wind and rain Bar 30.35 All is well So ends this day

May 25/33

This Day comes in with S.E. wind and clear Bar 30.35 Crew painting deck and white on hull 4 P.M. S.W. wind and fog Bar 30.30 All is well So ends this day

May 26/33

This Day comes in with S.W. wind and clear Bar 30.30 Crew painting hull on Port Side 4 P.M. S.W. wind and clear Bar 30.25 All is well So ends this day

May 27/33

This Day comes in with S.W. wind and clear Bar 30.11 Crew painting deck on Starboard Side and cleaning ship for Sunday 4 P.M. S.W. wind and clear Bar 30.00 All is well So ends this day

May 28/33

This Day comes in with N.E. wind and rain Bar 30.05 Mate and Bill Perry on watch 4 P.M. S.W. wind and cloudy Bar 30.15 All is well So ends this day

May 29/33

This Day comes in with S.E. wind and cloudy Bar 30.40 4 P.M. South wind and cloudy Bar 30.50 All is well So ends this day

May 30/33

This Day comes in with S.E. wind and cloudy Bar 30.55 Ernest Jennings and Joe Findato on watch 4 P.M. S.E. wind and cloudy Bar 30.45 All is well So ends this day