

Ship (sailed from) England towards Cape Horn 1806

HKF	Courses	Winds	Remarks on Saturday Sept 21
2 3	SWB	SE	Moderate Winds with flights of Rain
4 3	SE	South	throughout these 24 hours
6 3	SEB	SW	at 1 P.M. tack to the W. at 2
8 3			3 tack to the E. saw a strange
10 3	SE	South	sail, bearing SE & Dist 3 or 4 Leagues
12 3			at 4 set all light sails at 10 tack then
2 3	SE	SW	in again
4 3			rather part the winds blowing about
6 3	SEB	SW	between SE & SW at 3 tack to
8 3	SE	South	the West in hopes of a continuance of
10 3	W	SW	the SE breeze which then blew but
12 3	SE		soon the wind came to SW which

Course 2 Dist 17 Lat 33 Long 33

HKF	Courses	Winds	Remarks on Sunday Sept 22
2 3	W	SW	Commences brisk winds at 1 P.M.
4 3	SW	SE	plying towards on the tack that is most
6 3	W	S	favourable, at 1 P.M. tack to the
8 3			W. at 1 P.M. tack to the E.
10 3			After having taken in light sails by the
12 3			wind, at 4 A.M. tack to the W.
2 3	SE	SW	and stood on during the remaining part
4 3	SEB		of these 24 hours having brisk breezes
6 3			and squalls of Rain, and a very uneven
8 3	SE	South	sea on - People unemployed as usual
10 3	W		on Sunday
12 4			No OBS.

Course 2 Dist 17 Lat 33 Long 33

Ship (sailed from) England towards Cape Horn 1806

HKF	Courses	Winds	Remarks on Monday Sept 23
2 3	SWB	SE	Commences moderate southerly winds &
4 3	W	SW	some light squalls of Rain
6 3	W	SW	steering to the W. by the wind with
8 3			all sail set at 10 P.M. tack in
10 3	W	SW	the outer gill and Mr. T. & J. & J.
12 3	W	SW	take the lower yard Stays, at 10 P.M. the
2 3			Middle & Lateral parts continues brisk
4 3	W	SW	winds, and flying Clouds still headed to
6 3	W	SW	the W. with very contrary winds to
8 3	W	SW	going Southward, without the Main sail
10 3			repaired etc. and hauled it again
12 2			set a new Rope for a Remaining and

Course 2 Dist 22 Lat 33 Long 33

HKF	Courses	Winds	Remarks on Tuesday Sept 24
2 3	W	SW	Light Winds and fine weather through
4 3	W	SE	out there 24 hours steering to the
6 3			South Westward close by the wind in
8 2			hopes of meeting with the wind more
10 2			favourable as we draw Southward
12 2			first part repaired the outer gill
2 2			at 3 P.M. set it, and all of the
4 2			Staysails, Lateral parts shifted the
6 2			Staysails found the new one
8 2			to need nothing but Mr. T. & J.
10 3			shifted the Lateral Staysails to End
12 4			Empty, & at many necessary jobs

Course 2 Dist 22 Lat 33 Long 33