

1906. March. 1906

Sunday 18 Fine weather Watch ashore all day.

Monday 19 This day employed in painting davits and barriers.

Tuesday 20 Employed these 24 hours in painting 1 vessel outside.

Wednesday 21 Employed these 24 hours in painting 6 vessel outside.

Thursday 22 Employed these 24 hours in painting boats.

Friday 23 Employed these 24 hours in painting boats.

Saturday 24 Got some water and did other small jobs.

Sunday 25 Watch ashore all day.

Monday 26 Employed these 24 hours in doing various small jobs.

1906. March. 1906.

Tuesday 27 Employed these 24 hours in doing various jobs one watch on shore all day.

Wednesday 28 Employed in doing a little painting and other jobs. one watch on shore all day.

Thursday 29 Doing almost nothing one watch on shore all day.

Friday 30 Rafted some water today and did other things one watch on shore.

Saturday 31 Cleaning up vessel one watch on shore.

Sunday