

Westport March 23rd 1894Tour of Westport
To Theodore P. Davis D.

March 23 rd	4 hours Labor	X \$1.05
" "	Line and nail	X .35
" 24 th	10 hours Labor	X 1.75
" "	2 Down Knobs	X .24
" "	Drives	X .14
" 25 th	3 hours Labor	X .52
" "	Head Pin Lumber	X .30
" 26 th	5 hours Labor	X .88
" 27 th	10 " "	X 1.75
" 28 th	10 " "	X 1.75
" 29 th	Freight on Lumber	X 2.50
April 2 nd	10 hours Labor	X 1.75
" "	Nails	X .48
" "	Blind Fastenings	X .24
" "	Window Fastenings	X .21
" "	Freight on Lumber	X 1.00
" 3 rd	10 hours Labor	X 1.75
" "	4 25 [¢] Pick Poles	X 8.50
" "	3 50 [¢] Pick Poles	X 6.10
" "	130 feet Branch	X 1.95
" "	3 Fork Hooks	X .15
" 4 th	10 hours Labor	X 1.75
" 5 th	10 " "	X 1.75
" "	Nails	X .75
" 6 th	1 hour Labor	X .17
" "	4 Locks	X 1.40
" "	some Peavee	X .02
" 7 th	10 hours Labor	X 1.75
" "	Nails and screws	X .27

April 10th 10 hours Labor \$ 1.75

" "	2 Locks	+ 1.40
" 17 th	4 Locks	4.42 + 1.40
" 18 th	34 Blind Fastenings	1.62 + 1.70
" 18 th	5 hours Labor	X .87
" 21 st	10 hours Labor	X 1.75
" "	2 Down Knobs	X .24
" "	Drives	X .14
" "	850	
" "	560	
" "	610	
" "	195	
" "	21.95	
" "	854.81	
" "	162	

Westport Aug 4th 1894Tour of Westport
To Theodore P. Davis D.

Aug 4 th	1 Down Bolt	X .10
" "	2 Windows Springs	X .20
" "	4 hours Labor	X .70
Nov 10 th	7 Windows Fastenings	X .48
" "	Glass and Putty	X .18
" "	4 hours Labor	X .80
" 17 th	2 1/2 hours Labor	X .50
Jan 10 th	1 Lock	X .20
" "	2 windows Fastenings	X .14
" "	1 Board	X .30
" "	4 hours Labor	X .80
" "		\$ 4.42

Tour of Westport 1894

Dec 27 th	To Theodore P. Davis D.	
" "	10 hours Labor	X 1.75
" "	5 hours Labor	X 1.00
" "	1 Board	X .30
" "	1 Board	X .30