

LOCATION 3100 E MONUMENT ST.

OWNER \_\_\_\_\_

OCCUPANCY CLASS \_\_\_\_\_ CONSTRUCTION TYPE \_\_\_\_\_

HEIGHT { \_\_\_\_\_ STORIES  
 \_\_\_\_\_ FEET AREA \_\_\_\_\_ SQ. FT.

VOLUME \_\_\_\_\_ CU. FT. CERTIFICATE NO. \_\_\_\_\_

DIV. 7  
 SEC. 18  
 BL'K 1631-32  
 LOT 12  
 B'L'DG \_\_\_\_\_

APPLICATION RECEIVED	PURPOSE OF APPLICATION	PERMIT		CONSTRUCTION COST	DATE OF COMPLETION	REMARKS
		NUMBER	DATE			
7/12/37	Regrade 2 <sup>nd</sup> floor porch with asbestos shingles	54443	7/13/37	10 <sup>00</sup>		
1/28/46	Repair redwood roof above front porch	57945	1/28/46	10 <sup>00</sup>		
10/29/46	side walls of garage Repair garage doors, replace	48282	10/30/46	20.00		
8-29-52	Apply Bondstone	133976	9/4/52	2,500. <sup>00</sup>		
10-13-52	Install 15 by Concrete floor slab	136625	11/6/52	400 <sup>00</sup>	Plans # 879	B2A652-52