

INCORPORATED UNDER THE LAWS OF THE STATE OF NEW YORK.

VICE-PRESIDENT, FRANK B. DECKER.

PRESIDENT, GEO. W. DECKER.

SEC'Y AND TREAS., JAMES C. WELCH.

CLARKE SULKY CO.,

MANUFACTURERS OF

THE ELECTRIC BIKE.

BROCKPORT, N. Y., 189

A few of the fast ones who
use the Electric Bike.

ROBERT J.

JOHN R. GENTRY.

JOE PATCHEN.

COLERIDGE.

DIRECTION.

BOUNCER.

HAL POINTER.

MASCOT.

GENEVA.

THEODORE SHELTON.

BE SURE.

B B. P.

CONDUCTOR.

COL. KUSER.

COASTMAN.

RYLAND T.

GEO. ST. CLAIR.

PAT L.

ANGIE D.

SUSIE G.

SIR EDWIN ARNOLD.

to your old suerig. The wheel which you
speak of may have taken on some
imperfection. The tightening or loosening
of one spoke would affect the trueness
of the wheel though it should be enough
to notice in the manner you describe. It
may be possible that the ball race has become
loose and would say that it would
be well to have it examined by an expert
bicycle repair man. It would then if
squared up do you until we are able to
get you up something heavier. It may
be too that it has not quite gone
together just right. That nickleed cap
may have got slightly bent or may
not quite fit. It may need filing or
fitting over. I only write this so as
to aid you in getting things right