

January the 13 1882

Mr E B Emory Letter to James Latman

To Putting in 3 fork hanel	1.00
To 1 Bil hook hanel	35
To Setting an rehetting saw	3.0
To Putting in plough beam	1.25
To Speisher hanel an 2 Rounds in	25
To Putting in small hanel	50
To Speisen plow hanel 1 round	37
To Making Sabel tree	40
To Making Main tree to wagon	50
To Making forboard to wagon	75
To Putting round in plough	10
To Changing plough beam	25
To Putting in plough hanel	62
To 3 rounds in plough	30
To 1 Plough beam	1.25
To filling Auger	10
To Putting in plough beam	1.50
To 1 Sane Slat harrow	50
To 1 Pair of harness	50
To Putting in too rounds in plough	20
	\$10.99