

We whose names are hereto
 subscribed have been on board the
 Majestic Ship Diadem and taken a
 strict and careful survey on the leak
 complained of and find as follows viz.

That the Ship makes on an
 average one ^{INCH} leak per hour at anchor.

Aboard the fore hold on the
 larboard side we find a leak in our
 opinion from a bolt about four feet
 under water.

After part of the After hold
 we find a leak supposed from a bolt
 about four or five feet under water.

The lead scuppers on the lower
 Deck have worked and broke the rails in.

We are of opinion the Ship
 might