

Journal from along the West Coast towards of Patagonia

H	K	F	COURSES.	WINDS.	Therm.		Barom.	REMARKS.	18 th					
					Air.	Wat.								
								Wednesday Feb 9 th						
1								Took John Hines from the Hospital at 11 AM weighed anchor and started for the Liege Ramaz wind blowing hard W S W.						
2														
3														
4														
5														
6														
7														
8														
9														
10														
11														
12														
1														
2														
3														
4														
5														
6														
7														
8														
9														
10														
11														
12														
COURSE.			Distance.	Lat.	Long.		Dist by Wheel.	No. Revolutions.	Lbs. Steam.	Cal-Of.	Coal Consumed.	Coal on Board.	Barometer.	Variation of Com.

H	K	F	COURSES.	WINDS.	Therm.		Barom.	REMARKS			
					air.	Wat.					
								1878 Thursday Feb 20th Laying at Fresh Water Bay generally very cold some snow and hail wind S S W			
1											
2											
3											
4											
5											
6											
7											
8											
9											
10											
11											
12											
1											
2											
3											
4											
5											
6											
7											
8											
9											
10											
11											
12											
COUSE.	Distance	Lat.	Long.	Dist. by Wheel.	No. Revolutions.	Lbs. Steam.	Gal. Oil.	Coal Consumed.	Coal on Board.	Barometer.	Variation of

Journal from along the West Coast towards of Patagonia.

H	K	F	COURSE.	WINDS.	Therm.		Barom.	REMARKS.	1876		
					Air.	Wat.					
1								Friday Feb 11 th			
2								Heighed anchor at 8 a.m. started in			
3								the southward bound SSW			
4											
5											
6											
7											
8											
9											
10											
11											
12											
1											
2											
3											
4											
5											
6											
7											
8											
9											
10											
11											
12											
	Distance.	Lat.	Long.	Dist. by Wheel.	No. Revolutions.	Lbs. Steam.	Coal-Off.	Coal Consumed.	Coal on Board.	Barometer.	Variation of Comp.

H	K	F	COURSES.	WINDS.	Therm.		Barom.	REMARKS.	1871
					Air.	Wat.			
1								Saturday Feb 12 th	
2								Went into Port Fanning at 3 P. M. sun	
3								the boat ashore for wood blowing hard	
4								S.W.	
5								4 P. M. weighed anchor and started	
6								southward wind W pleasant but	
7								cold	
8									
9									
10									
11									
12									
1									
2									
3									
4									
5									
6									
7									
8									
9									
10									
11									
12									
Distance. Lat. Long. Dist. by Wheel. No. Revolutions. Lbs. Steam. Cal-Gr. Coal Consumed. Coal on Board. Barometer. Variation of Comp.									0.020