

Thursday November 12/31

This Day comes in with Strong S.W. wind + Cloudy Bar 30.6.
John Tilton work today Mate Leon in charge.
4 P.M. Pumps + Lights Alright. Strong S.W. winds + Cloudy. Bar 30.4.
So Ends this Day.

Friday November 13/31

This Day comes in with a heavy over cast + Strong S.W. wind.
Bar 30.2. John Tilton not down today.
All is well on board ship.
4 P.M. wind S.W. + clear Bar 30.1.
Pumps + Lights Alright. So Ends this Day.

Saturday November 14/31

This Day comes in with Strong N.W. winds + clear Bar 30.5
plumbers Brock up Tailit system today.
Mate in charge 4 P.M. Strong N.W. winds + Cloudy. Bar 30.5.
So Ends this Day.

Sunday November 15/31

This Day comes in with Strong N.E. winds + Cloudy. Bar 30.7
All is well Mate in charge.
4 P.M. Strong S.E. wind + cold. Bar 30.7.
Jack Frates on watch for the night.

Monday November 16/31

This Day comes in with rain + light N.E. winds Bar 30.7.
4 P.M. light N.E. wind Bar 30.7
Jack Frates on watch

Tuesday November 17/31

This Day comes in Foggy with Light W. wind + Cloudy.
Bar 30.7. All is well.
4 P.M. no wind + Fog. Bar 30.6.
Jack Frates Night watchman.

Wednesday November 18/31

This Day comes in with Strong Southly winds + Cloudy.
Bar 30.5. All is well Mate in charge.
Strong S.W. winds + Cloudy. 4 P.M. Bar 30.5
Jack Frates Night watchman.

Thursday November 19/31

This Day comes in with Light N.E. winds + Fog and somewhat colder Bar 30.7. All is well.
4 P.M. Strong N.E. wind + cold. Bar 30.7
Ernest Jennings Night watchman.

Friday November 20/31

This Day comes in with Light N.E. winds + thick Fog. Bar 30.8.
All is well. Mate in charge.
4 P.M. Light N.E. wind + Foggy. Bar 30.8.

Saturday November 21/31

This Day comes in with Heavy Fog + Light N.E. winds. Bar 30.8.
4 P.M. Light S.W. wind + clear Bar 30.8.

Sunday November 22/31

This Day comes in with Light S.W. winds + Foggy Bar 30.8.
4 P.M. Light S.W. wind + clear Bar 30.8.
So Ends this Day.