

May 28/32 This Day comes in cloudy  
+ strong S.W. winds Bar  $30\frac{1}{10}$   
blew up ship for Sunday  
4 P.M. Strong S.W. winds + fog Bar  $30\frac{1}{10}$

May 29/32 This Day comes in Fair  
with strong N.W. winds Bar  $30\frac{1}{10}$   
4 P.M. Strong N.E. winds + cloudy Bar  $30\frac{4}{10}$   
All is well. Mate in charge.

May 30/32 This Day comes in  
pleasant with Light S.W. wind Bar  $30\frac{5}{10}$   
Ship dress with one Hundred + eight  
house flags for Memorial. All is well  
4 P.M. Light S.W. wind Bar  $30\frac{2}{10}$   
So Ends this Day.

May 31/32 This Day comes in Fair  
with strong S.W. wind + cloudy.  
Bar  $30\frac{6}{10}$ . Crew straightening out Loris  
on main Mast + Foremast.  
4 P.M. Strong S.W. wind. Bar  $30\frac{4}{10}$

June 1/32 This Day comes in pleasant.  
Light S.W. wind Bar  $30\frac{5}{10}$   
Crew painting W. Side Deck  
Finish painting port side with Black  
4 P.M. Light S.W. wind + very warm Bar  $30\frac{5}{10}$

June 2/32 This Day comes in Fair  
with Light N.E. winds + cloudy.  
Bar  $30\frac{1}{10}$  Crew painting rail on Deck.  
Put Four Boats on ship + painted rail  
4 P.M. wind S.W. + cloudy Bar  $30\frac{6}{10}$

June 3/32 This Day comes in cloudy.  
with Light S.W. winds. Bar  $30\frac{6}{10}$   
4 P.M. Strong S.W. winds + rain. Bar  $30\frac{6}{10}$

June 4/32 This Day comes in Fair  
with strong S.W. winds. Bar  $30\frac{4}{10}$   
blew up ship for Sunday  
4 P.M. Light S.W. wind Bar  $30\frac{4}{10}$

June 5/32 This Day comes in Hot.  
No wind Bar  $30\frac{3}{10}$ . All is well.  
4 P.M. Light S.W. wind + clear Bar  $30\frac{4}{10}$

June 6/32 This Day comes in Fair  
with Light S.W. winds Bar  $30\frac{2}{10}$   
Crew again Warden Mast.  
4 P.M. Strong S.W. wind + rain Bar  $30\frac{1}{10}$