

October 21/34

This Day comes in with N.W. wind and clear Bar 29.90. Crew Jenning, Louis Sylvia and Bill Perry on watch 4 P.M. N.E. wind and cloudy Bar 29.80. All is well so ends this day.

October 22/34

This Day comes in with S.E. wind and cloudy Bar 29.80. Crew working in blacksmith shop 4 P.M. N.E. wind and rain Bar 29.70. All is well so ends this day.

October 23/34

This Day comes in with N.E. wind and rain Bar 29.60. 4 P.M. N.E. wind and rain Bar 29.60. All is well so ends this day.

October 24/34

This Day comes in with N.E. wind and cloudy Bar 29.80. Crew taking whaleboats off ship 4 P.M. East wind and clear Bar 29.95. All is well so ends this day.

October 25/34

This Day comes in with North wind and clear Bar 29.90. Crew working on Wanders Mast 4 P.M. N.E. wind and clear Bar 29.85. All is well so ends this day.

October 26/34

This Day comes in with South wind and cloudy Bar 29.80. Crew working on Wanders Mast 4 P.M. S.W. wind and cloudy Bar 29.70. All is well so ends this day.

October 27/34

This Day comes in with N.W. wind and clear Bar 29.70. Crew cleaning ship for Sunday 4 P.M. N.W. wind and clear Bar 29.70. All is well so ends this day.

October 28/34

This Day comes in with Strong W.N.W. wind and clear Bar 29.70. Mate, Louis Sylvia and Joe Furtado on watch 4 P.M. Strong W.N.W. wind and cloudy Bar 29.60. All is well so ends this day.

October 29/34

This Day comes in with N.W. wind and clear Bar 29.90. Crew taking down Wanders rigging and covering whaleboats 4 P.M. Strong S.W. wind and rain Bar 29.90. All is well so ends this day.

October 30/34

This Day comes in with S.W. wind and clear Bar 29.95. Crew painting bulwark's grey 4 P.M. S.W. wind and clear Bar 29.95. All is well so ends this day.