

Ship Thaverly Homeward Bound February 1858

Tuesday Feb the 8th 1858
A strong breeze from N to W
Steering E by S
Employed fitting a fore yard
Middle part Rainy leak 1500 strokes

Lat Long
50-48 102-09

Wednesday Feb the 9th
The fore part strong breeze from
W to S steering E at 4 1/2 m. sent
down the old fore yard & sent up
a nether one

Middle part strong breeze from
W steering E by S some rain
Latter part light breeze from
S heading E & sent up a
new top gallant studding sail boom
leak 1200 strokes

Thursday Feb the 10th
The fore part light breeze from S
heading E S E Middle & latter
parts fresh breeze from N E
heading E S attended with thick
Rainy weather

Friday Feb the 11th
A moderate gale all these 24 hours
from N E to E heading S by S
the weather thick and Rainy

Saturday Feb the 12th
The fore part strong breeze from
N heading E S E Middle & latter
parts light breeze from E S at 7 1/2 m
wore ship heading N E attended with
thick Rainy weather leak 1000 strokes

Ship Thaverly of New Bedford Homeward Bound

February 1858

Wednesday Feb the 3rd 1858
A fresh breeze from W to WNW
Steering E by S
Middle part Rainy

Lat Long
46-44 125-57

Thursday Feb the 4th
A strong breeze from WNW
to W S steering E by S
passing temporary showers
Ship's leak 400 strokes

47-08 122-16

Friday Feb the 5th
A strong breeze from S by W to W
steering E S E by S saw porpoises
split the fore royal & sent

48-38 118-17

Saturday Feb the 6th
A strong breeze from W to S W
steering E by S at 4 1/2 m
carried away the fore yard in
the shive & sent up the old
studding sail boom & yard in
a squall Latter part light
breeze from the southward
leak 4000 strokes

48-54

Sunday Feb the 7th
The fore part light breeze from the
southward & sent up the old
main yard & sent up a new one
Middle & latter parts fresh breeze
from N to W steering E S E by S
Employed fitting the old main yard
for a fore yard leak 2000 strokes