

Journal from

towards

18

H	K	F	COURSES	WINDS	Therm. Air. Wat.	Barom.	REMARKS
1							12 1/2 20th
2							15 days
3							30
4							10
5							
6							
7							
8							
9							
10							
11							6
12							35
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

Journal from

towards

18

H	K	F	COURSES	WINDS	Therm. Air. Wat.	Barom.	REMARKS
1							18 mds
2							
3							
4							
5							
6							
7							
8							
9							
10							1800
11							
12							
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

COURSE	Distance	Lat.	Long.	Dist. by Wheel	No. Revolutions	Lbs. Steam	Cut-Off	Coal Consumed	Coal on Board	Barometer	Variation of Comp.
--------	----------	------	-------	----------------	-----------------	------------	---------	---------------	---------------	-----------	--------------------

COURSE	Distance	Lat.	Long.	Dist. by Wheel	No. Revolutions	Lbs. Steam	Cut-Off	Coal Consumed	Coal on Board	Barometer	Variation of Comp.
--------	----------	------	-------	----------------	-----------------	------------	---------	---------------	---------------	-----------	--------------------

H	K	F	COURSES	WINDS	Therm. Air. Wat.	Barom.	REMARKS
1							184 last worked
2							level bring up at the Cape on the side of Island
3							in 15 fathoms level the next level by the Cape no house on S.P. Island
4							weather permits work and land taking done go down to beach and saddle
5							remain on beach until deal up get good knockdown 657 tons
6							few to be got dead to windward of Island 30 to 40 not done
7							
8							Pig Island same can work Apastles from Pig Island in boats
9							but have laid at anchor at last end on South side
10							20 fathoms produced 2 to 300
11							another Island named by me some 16 years ago called it
12							the principal of business at sea and the party done very well in the season it is a small Island anchorage Rocky
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

H	K	F	COURSES	WINDS	Therm. Air. Wat.	Barom.	REMARKS
1							P & anchor at landing walk on Island to Rocks
2							down Jacks ladder
3							Rocky on Hog Island
4							
5							Islands I chat on all west coast
6							for trade in 1845
7							
8							Capt John Rol
9							new lands
10							Cape Town
11							Da
12							
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

COURSE	Distance	Lat.	Long.	Dist. by Wheel	No. Revolutions	Lbs. Steam	Cut-Off	Coal Consumed	Coal on Board	Barometer	Variation of Comp.
--------	----------	------	-------	----------------	-----------------	------------	---------	---------------	---------------	-----------	--------------------

COURSE	Distance	Lat.	Long.	Dist. by Wheel	No. Revolutions	Lbs. Steam	Cut-Off	Coal Consumed	Coal on Board	Barometer	Variation of Comp.
--------	----------	------	-------	----------------	-----------------	------------	---------	---------------	---------------	-----------	--------------------