

Remarks on the Board Barb Berta

Monday

May 15th 1911 Leaving from Lamerica. Tuesday 16th at 11 a.m.
at 9 a.m. anchor on St. Eustatius

Monday

May 22nd 1911 Leaving from Statius at 11 clock
fine clear weather and light breeze wind from S
end of day

Tuesday

May 23rd 1911 p.m. light breeze and fine clear weather
wind from NE close hauled all sails set all the
Islands in sight - Lat: 17.47 N Lon: 63.23 W

Wednesday

May 24th 1911 p.m. fine clear weather wind from NE all sail
set - Course NW - Saw two steamers bound N
and school of killers end of day Lat: 18.70 N Lon: 63.50 W

Thursday

May 25th 1911 ~~at~~ a.m. light breeze and fine clear weather
at 5 p.m. squally with rain wind from NE
all sails set - Course NW - Saw two steamers
and two sails bound N end of day

Friday

May 26th 1911
p.m. light breeze and fine clear weather wind from
SE all sails set - Course NW - Watch employed
on ship duty - Saw nothing. end of day.
Lat: 21.00 N Lon: 65.23 W

Saturday

May 27th 1911 day began with light breezes and fine clear
weather at p.m. wind hauled to northward
squally with rain taking on light sails
Course NW - Saw a steamer bound S
end of day. No observation sun obscure

Remarks on the Board Barb Berta

Sunday

May 28 1911 day began with fine weather at 3 p.m.
squally with shower of rain wind from SE.
all sails set - Course NW - Saw nothing

Monday

end of day. Lat: 23.31 N Lon: 66.40 W

Tuesday

May 29th 1911 p.m. fresh breeze and cloudy weather
wind from SE all sails set - Course NW

Tuesday

Saw nothing. end of day. Lat: 25.36 N
Lon: 67.44 W

Wednesday

May 30th 1911

p.m. steady breeze and haze weather wind from S
all square sails set - Course NW - employed on ship
duty. end of day. Lat: 27.54 N Lon: 68.38 W

Thursday

May 31 1911 p.m. strong breeze and squally with rain
wind from SE Course NW - Ship running
under topsails and main gallant sail
Saw steamer bound S John J. Cornell
Sick of duty. Pedro Gomez Sick of duty
end of day. No observation sun obscure

Thursday

June 1st 1911 p.m. steady breeze and cloudy weather
wind from S all sails set - Course NW -
Watch employed on ship duty - Saw nothing
end of day. Lat: by dead Reckoning 31.52 N Lon: 70.27 W

Friday

June 2nd 1911 p.m. light breeze and fine clear weather wind from
NW all sails set close hauled - Watch employed on
ship duty. Saw nothing. end of day.

Saturday

June 3rd 1911
Lat: 32.19 N Lon: 70.50 W

p.m. calm all day and haze weather
all sails set - Watch employed on ship duty.
Saw nothing end of day.
Lat: 32.40 N Lon: 71.11 W