

1000-1014

LOCATION

1016 Guilford Ave

OWNER

OCCUPANCY CLASS

CONSTRUCTION TYPE

HEIGHT

STORIES

AREA

SQ. FT.

FEET

VOLUME

CU. FT.

CERTIFICATE NO.

DIV.

11

SEC.

12

BL'K.

508

LOT

2-2A

B'L'DG

| APPLICATION RECEIVED | PURPOSE OF APPLICATION                               | PERMIT |          | CONSTRUCTION COST | DATE OF COMPLETION | REMARKS    |
|----------------------|--|--------|----------|-------------------|--------------------|------------|
|                      |  | NUMBER | DATE     |                   |                    |            |
| 4-28-34              | Replace Wood Sprinkler Tank                          | 5846   | 10-15-34 | 640 <sup>00</sup> |                    |            |
| 4-3-37               | Closing <sup>portion of</sup> 2 windows on 2nd floor | 2741   | 4-3-37   | 100 <sup>00</sup> |                    |            |
| 8-5-42               | use for parking lot                                  | 7195   | 8-22-42  | —                 | 10-30-42           |            |
| 10/25/41             | Erect Paige fence around lot                         | 6791   | 10/25/41 | 400 <sup>00</sup> |                    | 1000-14-2A |
| 7-13-53              | Roof tank inspection <sup>53-54</sup>                | 147087 | 7-13-54  | —                 |                    |            |
| 11-15-55             | "Inspection"-1956-1957                               | 183532 | 11-25-55 | —                 | 11-28-55           |            |
| 4-13-59              | " " - 1958-1959                                      | 225335 | 4-13-59  | —                 | 4-14-59            |            |