

LOCATION 419-33 E Oliver St

OWNER Muskin Shoe Co

OCCUPANCY CLASS _____ CONSTRUCTION TYPE _____

HEIGHT { _____ STORIES _____ AREA _____ SQ FT
 _____ FEET

VOLUME _____ CU FT CERTIFICATE NO _____

DIV. 12
 SEC 10
 BL'K 1128
 LOT 48
 B'L'DG _____

APPLICATION RECEIVED	PURPOSE OF APPLICATION	PERMIT		CONSTRUCTION COST	DATE OF COMPLETION	REMARKS
		NUMBER	DATE			
4-24-24	Erect 1 Addn ¹ Story ^{Factory} Ten Bldg	2194	5-7-24	12,000 ⁰⁰		
12-19-32	Repair Conc. Exterior Surface	10008	12-19-32	100 ⁰⁰		
5-5-33	Replacement & Repair ^{Conc.} disintegrated	13214	5-5-33	1500 ⁰⁰		
7-27-36	Repair Fire Damage	6409	7-27-36	17 ⁰⁰		
	Violation Notice	V-12458	8-31-55	Rectified	11-19-56	419
3-7-61	Repair 1st Floor ^{Steps} Bldg ^{Replaced by 2nd} with 1st floor	251396	4-10-61	9275 ⁰⁰	6-8-61	01-484
4-11-61	Repair 1st floor ^{Steps} Bldg	251456	4-11-61		6-5-61	419-33 Paved