Sta 371+ Drain Sta 350 to Sta 398 mostly sandy farm land covered with underbrush with a high absorbtive factor
No stream channel evident at line crossing.
Area 300 ac

Sta 410+ Drains from 398 to 418 could be taken down side of cut in concrete trough and out through the cut ditches.
Sandy Ridge run off light.
Area 69 ac

Sta. 428+ Drains from Sta. 418 to 460.
Sandy farm land, moderate slope high absorbtive factor no definite stream channel.
Area 260 ac

Sta 478+ Drains Sta 460 to 512 nearly flat farm land no visable channel.
Area 167 ac

Sta 527+ Drains Sta 512 to 538+ Side hill covered with thick underbrush.
Area 48 ac.

Note
Not bed rock showing in any of the stream beds.