

Barque Courier. Bound South.

Wednesday 25th.

Commences with light winds from W. steering S. by E. by the wind. Employed in fitting Rigging. Middle & Latter parts light airs and calms. Capt. Hamblin fitting, and caulking the Wood ends, on Starboard side of cutwater, to stop the leak. After finishing, tried both Pumps, but got but little water, it being calm. Employed in fitting Head Rigging.

Latth 11.00

Longth 153.47.

Thursday 26th.

Commences with light airs and variable. Fitting Head Rigging. Tried the Pumps, got no water. Middle & Latter parts light airs and calms, Employed in fitting Rigging. Genl in job, and repaired, and sent it out again.

Latth 12.10

Longth 153.22

Friday 27th.

Commences with a fine breeze from N.W. steering S. by E. took a squall from S.W. with rain, tried the Pumps, got no water. Middle & Latter parts. Squally with rain. Broke out after hold and stowed over.

Latth 14.18

Longth 153.53

Barque Courier. Bound South.

Saturday 28th.

Commences with moderate winds from Westward, steering S. by E. Employed in fitting Rigging. Pumps attended to, but no water. Middle & Latter parts, squally with rain. Washed ship inside.

Latth 16.00

Longth 153.50

Sunday 29th.

Commences with squally, rainy weather wind N.W. course S. At 4. Washed the decks, and served the Pumps. Middle & Latter parts, strong winds from N.W. steering S. by E. frequent squalls of wind and rain. Ship under snug sail. Leak stopped, getting no water from the Pumps.

Latth 18.35

Longth 152.50

Monday 30th.

Commences with a gale from N.W. with strong squalls of wind, and a little rain. At 4 tried the Pumps, No water. Took craft out of W. Boat, and secured her to the davit heads, and Rins bolts on deck. Middle & Latter parts strong gales from N.W. course S by E.

Latth 21.38

Longth 153.00