

Cath. Chuam. 1 shot in 1841 - Pop and heavy cath. dicty. Sh. att. &
Cath. bottom off in 1844 -

Shells in 1840 - Cyp. in 1844 - in aprils top can be seen
Bottom Cyp. ship put in good order

Shuttles & Coffin Buoy - April 43 Top caulked & Bottom Capped
Ship put in good order - In 1852 Top caulked &
Bottom Capped, Ship in good order one year more
In June 1856 - Ship caulked all over and put in good order
bottom sheathed & coppered In 1861 Top caulked & Bottom
Coppered ship put in good order. In April 1866
caulked all over Bottom sheathed & coppered and
put in good order In Oct 1871 had new
upper Deck & some other repairs about the
top ship put in good order Bottom Capped

Bathurst in 1839. - Not a bad cargo & smooth, new fore and
main mast, ship put in good order in 1844. In July 1845 -
and Benck Calked Bottom examined and found good
Bottom Copper & put in good order. In March 1851 had
some ceiling taken out in lower hold on both sides
in wake of the Fore-mast. Several timbers found
rotten on both sides. Some ceiling taken out aft
in the W a few timbers found rotten. These
timbers were not replaced with new. Ship's top Calked
and put in fair order. Bottom Calked, sheathed
and coppered. Other than the rotten timbers in
the lower hold, the ship appears to be in fair
order to perform a voyage. In Nov. Oct.
1853, had ceiling out of lower hold. 40 timbers put in
new ~~stow~~ stem. new bows from the water edge up.
port new stern post. new transom. new planks.
port new lower deck & frame. lower deck frame
reconstructed. new upper deck & frame. new planks
new beams. new top sides. 3 new beam-hooks. ship
calked all over. Bottom sheathed and coppered.
Ship appears to be in good order. In Sept 1854
top calked - bottom coppered - Bark appears to be in fair order.
Examined to page 233