

391

May 1845

Bark Valparaiso of New Bedford
Built in Baltimore 1837 - 2 decks - 100 1/2 Tons - 18 ft. Copper
2 Chains 1 1/2 - Anch Fair - Rigging Fair - Rat A2

Calk all over Sheath & Copper put in fair late order - 1845 -
Top caulked & Bottom coppered Ship, Spars, Rigging
in good order in 1848 In 1852 Top caulked & Bottom
put in good order Wood ends on Bottoms
Caulked Bottom coppered - In August 1856 had
some repairs about the top - Ship caulked all over
bottom sheathed and coppered - and put in good order
In Sept. '57 had her top caulked and put in good
order; bottom coppered.

August 1847 Ship Virginia of New Bedford
Built in Mattapoisett 1836 2 decks - 316 Tons -
18 ft. Copper - 2 Chains 1 1/2 - 1 1/2 - Anch. Fair
Rigging - Sails good Rate A2

1847 Calk all over the name Sheath & Copper
Ship put in good order In 1851 Top caulked & Bottom
coppered ship in good order. In June 1855 Caulked all
over Bottom sheath & coppered. Ship in good order.
In Oct 1860 had a new stern part of a
new keel torn new planks on bottom
Bottom about one half caulked and
sheathed anew Bottom coppered Ship
put in good order

392

Sept 1851 Ship Vernon of New Bedford
Built in Medford in 1844. 2 decks 307 tons 18 ft copper
2 c.c. 1 1/2 + 1 1/2 in fair Sails & Rig fair Rate A2

In Aug 1857 Ship caulked all over and put
in good order Bottom sheathed & coppered The
Ship appears to be a well built and strong vessel
In Aug 1858 caulked her top & Bottom copper. Ship in
fair order.

Bark Vigilant of New Bedford Wm Mathews
Built in Mattapoisett in 1852. 2 decks 138 tons 18 ft
2 c.c. 1 1/2 + 1 1/2 in good Sails & Rig fair Rate A1

Sheathed and Coppered in New Bedford in Jan 1852
In Aug 1855 had her top caulked and bottom
coppered Bark in good order.
In July 1859 caulked, sheathed and coppered - Bark
in good order In March 1865
had her top caulked and bottom coppered
new main mast and several other
new spars - Bark put in good order
In Aug 1870 caulked all over bottom
sheathed & coppered Bark put in good
order