

Oct. Ship Williams & Clark of New Bedford, 22 Decr. 1815 - 2 Decks - 221 Tons - 17 ft up Copper -
 1844 - 2 Chans 1. 1/4. Anch Fair - Rigging Fair - Rate A 2 1/2

Rebuilt in bottom in 1820 - New top in 1839 - New lower deck and frame. One stack was taken out all around timbers found good. Top caulked bottom copper ship put in good order. 1844 -

Oct 1848 New Plank & nearly all new timbers from the Ham Kishie & two stiches below the wales, Ceiling out in lower holes and all timbers replaced with new, new wales, ship caulked all over chummed, sheathed & coppered, ship was in good order for some time. In 1852 Top can three and put in good order. Bottom coppered. In June 1856, caulked all over, bottom sheathed and coppered. Ship put in good order - chains & dunnage good

1844 - Ship Williams & Clark of New Bedford, 22 Decr. 1815 - 2 Decks - 221 Tons - 17 ft up Copper -
 1844 - 2 Chans 1. 1/4. Anch Good - Rigging Good - Rate A 3

New masts, new rigging, new bowsprit, castles, chum and sheath in 1840 - Caulk and copper in 1844 -

June 1844 - Ship Willis of New Bedford, 22 Decr. 1815 - 2 Decks - 221 Tons - 17 ft up Copper -
 1844 - 2 Chans 1. 1/4. Anch Good - Rigging Good - Rate A 2 1/2

Water Sheath and copper in 1840 - In Sept 47 Coppered & sheathed & coppered In 1848 caulked about top Bottom was coppered anew. In Aug 1856 had some repairs about the top. Bottom copper. Ship in fair order.

In April 1857 had her Top caulked and put in fair order. Copper on bottom Patched. In April 1859 had her top caulked - bottom examined and put in fair order - bottom below the beams caulked and sheathed and coppered - top & beams caulked in 1857.

In May 1861 Top caulked and put in fair order. Copper on bottom patched.

In Oct. 1862 caulked all over - chummed, sheathed and coppered - new for rigging - Bark put in good order. In July 1865 top caulked and put in good order - bottom coppered.

1844 - Ship Washington of New Bedford, 22 Decr. 1815 - 2 Decks - 221 Tons - 17 ft up Copper -
 1844 - 2 Chans 1. 1/4. Anch Good - Rigging Good - Rate A 2 1/2

Had cutting out and 300 new timbers put in lower part, ceiling, and new plank outside from below wales up. New stem, new bows, several new beams in both deck frames, castles all over and sheath in 1842 and coppered. Top caulked and ship put in good order. Bottom not coppered in 1844 - Top caulked. Bottom coppered. Ship in good order for a voyage. In 1850 Top caulked. Had 4 streaks of ceiling taken out below the lower deck nearly all new top timbers & 5 new timbers put in below the lower deck new stanchions & new cleats & framed and near by a new top, caulked all over. Bottom sheathed & coppered. Still spars & rigging in good order. In 1853. Newly coppered and put in good order.

In July 57 had some fore masts below the wales. Ship caulked all over, bottom sheathed and coppered. Ship put in good order. In June 1861 Top and beams caulked, Garboard and wood end seams caulked. Bottom coppered.

Ship appears to be in fair order. In June 1865, had thirty new plank put in bottom. Bottom put in good order - timbers when exposed found sound. Ship caulked all over bottom sheathed & coppered.